


Follow these instructions and we've . . .

# Gotcha!

## CRD Ladder CRD Reach ADD



Icons: Clock, SpanSet box, Magnifying glass, Calendar (6, 12), Scissors, Thermometer.

+ 50°C (122°F)  
- 30°C (22°F)

Warning icon: !

Icons: Starburst, Knife, Fire, Funnel, Hand holding tool.

25

Icons: Sink, Detergent, Washing machine, 25°C (77°F), Bottle, SpanSet device.

< 25°C (77°F)

Icons: X, Thermometer, Sun, Cloud, Handgun, Scissors, SpanSet device, SpanSet box with arrow.

< 30°C (86°F)

OK? icon: Head with thought bubble.


Icons: Hand holding device, Gears, SpanSet device, SpanSet box, SpanSet device.

EN795 / 12kN MBS


Icons: House, UV, Cloud with rain, Envelope, SpanSet logo, www.spanset.com

# Gotcha CRD Ladder & CRD Reach



1




2












3



# Gotcha CRD Reach



# Gotcha ADD



Ladder & Reach

OK

